

Structure No.: 0500006

Route: 9005

Milepost: 0.30

Name: STONE HARBOR BLVD(CR657)/GREAT CHNL

CoMBIS Priority Repair Form

Bridge Owner - Maintenance Section

Beyond Capacity of Maintenance Dept. - Recommend Contractor Be Hired:

Contract Number:

Date Work Assigned:

Personnel Assigned:

What Was

Done/Materials Used:

Maintenance Comments:

Was Interim Work Completed:

Date Interim Work Flagged as Complete:

Date Final Work Completed:

Flagged as Complete By:

Photo	Category:	05 - Sidewalks/Safetywalks/Curbs, 60 - Priority Repair
	Description:	Bascule span south sidewalk, looking west. 18" x 3" broken/distorted section at east end.

3/4" tall
NOT serrated
Connecting Bar "Dovetail"

Hot Dipped Galvanized