- 1. Fabricate treads and platforms from welded or pressure-locked aluminum grating with 1-by-1/8-inch bearing bars at 7/16 inch o.c. and crossbars at 4 inches o.c. and with openings in gratings no more than 5/16 inch in least dimension.
- 2. Surface: Plain.
- 3. Finish: Mill.
- 4. Fabricate grating treads with cast-abrasive nosing and with steel angle or steel plate carrier at each end for stringer connections. Secure treads to stringers with stainless steel bolts.
- 5. Fabricate grating platforms with nosing matching that on grating treads. Provide toeplates at open-sided edges of grating platforms. Secure grating to platform framing with stainless steel bolts.
- D. Risers: Solid.
- E. Toe Plates: Provide toe plates around openings and at edge of open-sided floors and platforms, and at open ends and open back edges of treads.
  - 1. Material and Finish: Steel plate to match finish of other steel items.
  - 2. Fabricate to dimensions and details indicated.

## 2.7 FABRICATION OF STAIR RAILINGS

- A. Comply with applicable requirements in Section 055213 "Pipe and Tube Railings."
  - Rails may be bent at corners, rail returns, and wall returns, instead of using prefabricated fittings.
  - 2. Connect posts to stair framing by direct welding unless otherwise indicated.

## 2.8 FINISHES

- A. Finish metal stairs after assembly.
- B. Galvanizing: Hot-dip galvanize items as indicated to comply with ASTM A 153/A 153M for steel and iron hardware and with ASTM A 123/A 123M for other steel and iron products.
  - 1. Do not quench or apply post-galvanizing treatments that might interfere with paint adhesion.
  - 2. Fill vent and drain holes that are exposed in the finished Work, unless indicated to remain as weep holes, by plugging with zinc solder and filing off smooth.
- C. Apply shop primer to uncoated surfaces of metal stair components, except those with galvanized finishes and those to be embedded in concrete or masonry unless otherwise indicated. Comply with SSPC-PA 1, "Paint Application Specification No. 1: Shop, Field, and Maintenance Painting of Steel," for shop painting.
  - 1. Stripe paint corners, crevices, bolts, welds, and sharp edges.