


[illegible]

FOR SHOP USE:			QUALITY CONTROL CHECK		
INITIAL	HOURS	DATE			
CUT _____	_____	_____	_____	DIMENSIONAL	_____
FIT _____	_____	_____	_____	VISUAL	_____
WELD _____	_____	_____	_____	DATE	_____
PAINT _____	_____	_____	_____		

THE INFORMATION NOTED HEREON THIS DRAWING IS THE
PROPERTY OF DS IRON,LLC, INC. AND SHALL
NOT BE USED WITHOUT WRITTEN CONSENT.

DS IRON, LLC

MISCELLANEOUS METALS FABRICATOR AND ERECTORS
3121 WINDSOR DRIVE LANDISVILLE, PA 17538

PROJECT OWNER: -----			
PROJECT DESCRIPTION: WILLOWDALE CHAPEL			
PROJECT ADDRESS: 111 VINEYARD WAY, WEST GROVE, PA 19390			
CONTRACTOR: CEDAR KNOLL BUILDERS			
DRAWN BY: SSN	DATE: 02-26-18	PROJ. 2017-021 NO.:	REV #
CHECKED BY: VB	DATE: 02-26-18	DWG NO.: 143	
DWG DESCRIPTION: GRATING DETAIL			

WELDS: E70XX	REVISIONS			
HOLES: 13/16" DIA (U.N.O)	REV #	DWN BY	REVISION	DATE
MAT'L: A36 (U.N.O)	A	BMV	SUBMIT FOR APPROVAL	03-05-18
PAINT: SSPC-SP3 PER SPECS	0	ATH	SUBMIT FOR FABRICATION	03-29-18