




~~3021~~
PcMk - RMST1 - QTY 27

2" THICK METAL GRATE TREAD

OSIYO METAL FABRICATORS, L.L.C.

1801 N. INDIANWOOD AVE. BROKEN ARROW, OK 74012

PH: 918-258-4717 FAX: 918-259-1170


JOB NO: _____

DRAW DATE: 2/22/2018

DRAWN BY: RJS

CHECK BY: _____

RMST1



EL 9/11
PcMk - 6T1 - QTY **16**

2" THICK METAL GRATE TREAD

OSIYO METAL FABRICATORS, L.L.C.

1801 N. INDIANWOOD AVE. BROKEN ARROW, OK 74012

PH: 918-258-4717 FAX: 918-259-1170


JOB NO: _____

DRAW DATE: 2/22/2018

DRAWN BY: RJS

CHECK BY: _____

6T1



PcMk - RMST2 - QTY ONE

2" THICK METAL GRATE TREAD

OSIYO METAL FABRICATORS, L.L.C.

1801 N. INDIANWOOD AVE. BROKEN ARROW, OK 74012

PH: 918-258-4717 FAX: 918-259-1170

JOB NO: _____

DRAW DATE: 2/22/2018

DRAWN BY: RJS

CHECK BY: _____

RMST2