

Tank Car Replacement Grating Order Form

Quality Form
Original Date
Revision Level
Revision Date
Approved By
AAR CODE:


--/--/2018
Original
N/A

TFWG
Page 1 of 1

1) CAR NUMBER: EAGX 27073
2) DATE OF ORDER: March 30/22
3) QUANTITY: 1

A) STAMPED U-CHANNEL GRATING


LOCATION(S) _____
L- _____ in
W- _____ in
H- _____ in




B) BAR GRATING

Galvanized

LOCATION(S) A
L - 115 1/2 in
W - 11 3/4 in
H - 1 1/2 in




3/16 Thick




CROSS BAR SPACING 4" in
BEARING BAR SPACING 1 1/2" in

SERATED or - FLAT BAR




C) FIBERGLASS REINFORCED PLASTIC GRATING

LOCATION(S) _____
L- _____ in
W- _____ in
H- _____ in



MESH SPACING:
L: _____ in
W: _____ in



4) PICTURE UPLOADED TO FILE? YES NO